

Item: 5 - Airworthy Airframe

| | | |
|--|-----------------------|-----------------------------|
| Discrepancy Remove #1,3,4,5,6 cylinders ship out for overhaul and reinstall. | Hours 35.57 | Subtotal 6,226.70 |
|--|-----------------------|-----------------------------|

Corrective Action

Removed the following engine cylinders: 1- P/N 658172, S/N FA366, 3 - P/N 658172, S/N BB166, 4 - P/N 658172, S/N BB220, 5 - P/N 658172, S/N GA816, 6 - P/N 658172, S/N GA869. Installed repaired cylinders: 1- P/N 658172, S/N FA366, 3 - P/N 658172, S/N BB166, 4 - P/N 658172, S/N BB220, 5 - P/N 658172, S/N GA816, 6 - P/N 658172, S/N GA869 in accordance with TCM O/H manual M18. Cylinders repaired by Tim's Aircraft Engines Inc. cert. # T22R537Y under work order # R/O 10316.

Outside Repair:

- Tim's Aircraft Engines, Inc. - Invoice #10316, Labor: 462.80, Parts: 1,287.12 (Overhaul)
- Tim's Aircraft Engines, Inc. - Invoice #10316, Labor: 462.80, Parts: 1,287.12 (Overhaul)
- Tim's Aircraft Engines, Inc. - Invoice #10316, Labor: 462.80, Parts: 1,287.12 (Overhaul)
- Tim's Aircraft Engines, Inc. - Invoice #10316, Labor: 462.80, Parts: 1,287.12 (Overhaul)
- Tim's Aircraft Engines, Inc. - Invoice #10316, Labor: 462.80, Parts: 1,287.12

| Qty | Unit | Part Number | Description | Serial Number | Unit Price | Subtotal |
|-----|------|-------------|--|---------------|------------|----------|
| 1 | EA | 10-32326 | SPRING (P/O: 9348) | | 4.59 | 4.59 |
| 2 | EA | 10-32326 | SPRING | | 4.59 | 9.18 |
| 2 | EA | 401506 | WASHER (P/O: 16705) | | 12.51 | 25.03 |
| 1 | EA | 649965 | GASKET (P/O: 7803) | | 1.16 | 1.16 |
| 1 | EA | 652458 | Gasket Exhaust SS IO520 Con (NO BLOW) (P/O: 16041) | | 11.39 | 11.39 |
| 1 | EA | 654309 | SPACER (TCM) (P/O: 16810) (Ship: 20.00) | | 49.80 | 49.80 |
| 4 | EA | 658077 | Exhaust Lifter, Hydraulic (P/O: 16722) | | 214.00 | 856.00 |
| 3 | EA | 658088 | Intake Lifter, Hydraulic (P/O: 16722) | | 214.00 | 642.00 |
| 1 | EA | AA9144 | GASKET, PROP GOVERNOR SAME AS P/N MS9144-01 (P/O: 15203) | | 25.26 | 25.26 |
| 2 | EA | MS90726-34 | SCREW, HEX (P/O: 6781) | | 2.48 | 4.97 |

| | | | |
|--------------------------|--------------------------|---------------------------|-----------------------------------|
| Labor: \$6,226.70 | Parts: \$8,064.98 | Shipping: \$270.00 | Item Subtotal: \$14,561.68 |
|--------------------------|--------------------------|---------------------------|-----------------------------------|

Item: 6 - Airworthy Airframe

| | | |
|--|----------------------|-----------------------------|
| Discrepancy Comply with annual inspection. | Hours Flat | Subtotal 2,860.00 |
|--|----------------------|-----------------------------|

Corrective Action

I certify that this aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

| | | | |
|--------------------------|----------------------|-------------------------|----------------------------------|
| Labor: \$2,860.00 | Parts: \$0.00 | Shipping: \$0.00 | Item Subtotal: \$2,860.00 |
|--------------------------|----------------------|-------------------------|----------------------------------|

Item: 7

| | | |
|---|----------------------|-------------------------|
| Discrepancy Comply with pre inspection operational checks and record. | Hours Flat | Subtotal 0.00 |
|---|----------------------|-------------------------|

Corrective Action

Complied with pre inspection operational checks and recorded data.

| | | | |
|----------------------|----------------------|-------------------------|------------------------------|
| Labor: \$0.00 | Parts: \$0.00 | Shipping: \$0.00 | Item Subtotal: \$0.00 |
|----------------------|----------------------|-------------------------|------------------------------|